


TYPICAL WIRING DIAGRAMS FOR INSTALLATION OF LM1CC "LEVEL MASTER" BOWL LEVEL CONTROL

VIBRATORY HOPPER APPLICATION

DC MOTOR CONTROL APPLICATION







WARNING: Black lead must be connected to FUSED power.

TIME DELAY ADJUSTMENT:

- 1) DISCONNECT POWER!!
- 2) REMOVE COVER AND CIRCUIT BOARD
- 3) SET "ON DELAY" TO DESIRED VALUE (0-10 SECONDS)
- 4) SET "OFF DELAY" TO DESIRED VALUE (0-10 SECONDS)
- 5) REPLACE BOARD AND COVER



0 SECONDS - NO DELAY




5 SECOND DELAY



10 SECOND DELAY

NOTE: OTHER DELAYS ARE POSSIBLE ANYWHERE BETWEEN THESE 0-10 SECOND SETTINGS



LM1 REV-5